

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. 35Date : 26.07.21

It is certified that an inspection team headed by Joy Kumar Ming
Asst. Engr. (Name of Officers
 with designation) from PW & HD Ramgash (Name of
 Department/Office) inspected the Kendriya Vidyalaya, Baskakana
P.O. - Baskakana (Name & Address of
 the School) on _____ and found that the _____
Kendriya Vidyalaya Baskakana (Name of school) has safe
 drinking water facilities for the students and members of staff of the institution and is maintaining
 the hygienic sanitation condition in the school building & the campus as per the norms
 prescribed by the Central/State/U.T Govt.

The above valid for a period of One Year.

Signature with Seal : Jain
26.07.21Name : ASST. ENGINEER
Designation : D.W.&S. SUB DIVISION
PATRATU

To

Kendriya Vidyalaya
Baskakana
P.O. - Baskakana

(Name & Address of the Institution)